cura[1]
ABN 88 007 603 161
10 Gray Street, Kilkenny, South Australia 5009
Ph:1300-12-2273, 08-8268-8343 Fax: 08-8268-1455
sales@cura1.com www.cura1.com

30th September 2016

CLEANING PROCESS FOR CURA[1]

MONITORS, BED & CHAIR PADS, FLOOR MATS, CABLES & ACCESSORIES

1. Check equipment. If it is visibly damaged or torn, discard and order new equipment.
2. If there is no visible damage, then proceed to clean equipment.
3.. Ensure the edges and any creases and recesses of equipment are wiped / brushed, also around any openings on equipment and accessories.
4. For infection control base cleaning, a 2 step process is recommended. (Subject to site cleaning policies.)
    - Step 1: wipe down equipment and monitors with a neutral solution ie: soap based disinfectant.
    - Step 2: wipe down with a chlorine based solution of 1/1000 parts Sodium Hypochlorite solution.
5. Milton Solutions or Equivalent, Tuffie 5 Wipes and Clinell Universal Wipes can also be used.
6. If the item being cleaned is a Floor Mat and is soiled, lightly brush and wipe as above.
7. Leave to air dry. Pads and Mats should be stored flat.

Note:
Please check with local infection control procedures as they may vary from state to state.
Do not use any alcohol based wipes or solutions.

Please note that any liquid can potentially damage the electronic components inside the equipment, so care should be taken to wring excess liquid from cloth before wiping surfaces. (Do not spray any cleaning solution into or onto equipment.)